

PREVAILED

Roll Call No. _____

FAILED

Ayes _____

WITHDRAWN

Noes _____

RULED OUT OF ORDER

HOUSE MOTION _____

MR. SPEAKER:

I move that House Bill 1289 be amended to read as follows:

- 1 Page 1, line 10, after "675 IAC 21-3-1" insert ",".
- 2 Page 1, line 10, delete "675 IAC 21-3-2," and insert "**675**
- 3 **IAC 21-3-2**".
- 4 Page 2, line 8, after "order." insert "**However, for Rule 8.6.5.8 to**
- 5 **be inapplicable to an elevator under this subdivision, the elevator:**
- 6 **(A) must:**
- 7 **(i) be inspected not less than one (1) time per year by an**
- 8 **elevator inspector; and**
- 9 **(ii) have a category 1 pressure test, as described in Rule**
- 10 **8.11.3.2 of the Safety Code for Elevators and Escalators**
- 11 **as specified by ASME A17.1-2000, performed on the**
- 12 **elevator not less than one (1) time every six (6) months,**
- 13 **one (1) test a year to be performed in the presence of the**
- 14 **elevator inspector performing the inspection required by**
- 15 **item (i);**
- 16 **(B) must have a static four (4) hour full load test, as**
- 17 **described in ASME A17.1-2000, performed by an elevator**
- 18 **mechanic whenever the elevator has an unexplained loss of**
- 19 **hydraulic fluid, and may not be operated again until the**
- 20 **elevator mechanic accounts for the unexplained loss of**
- 21 **hydraulic fluid; and**
- 22 **(C) shall bear a disclaimer posted in the cab of the elevator**
- 23 **with the following wording: "This elevator does not meet**
- 24 **the latest safety requirements as published by the**
- 25 **American Society of Mechanical Engineers. If the**

1 **hydraulic elevator jack loses pressure, this elevator may**
2 **descend rapidly and hit with tremendous force, causing**
3 **injury and possibly death to individuals in the elevator.**
4 **Individuals ride at their own risk."".**

(Reference is to HB 1289 as printed February 9, 2005.)

Representative Tinch